



G0512A-G0812A SINGLE REDUCTION GEARMOTORS

SIZE	A	B	C	E	F	H	H1	I	N	P	P3	S	SLOW SPEED SHAFT					
													D	L	L2	T	U	W
G0512	4.33	4.92	.67	5.39	5.98	2.48	1.85	2.20	1.06	8.58	7.09	.43	.75	1.575	1-9/32	.829	3/16	1/4 UNF X .63 DP
G0612	4.72	5.31	.79	5.91	6.69	3.15	2.36	2.95	1.38	10.16	9.06	.55	1.00	1.969	1-9/16	1.106	1/4	1/4 UNF X .71 DP
G0712	5.91	6.69	.98	7.48	8.35	3.54	2.91	3.35	1.65	12.05	10.63	.69	1.25	2.362	2	1.359	1/4	1/4 UNF X .71 DP
G0812	6.30	8.46	1.18	8.11	10.43	3.94	3.82	4.33	2.36	13.86	12.68	.69	1.625	3.15	2-3/8	1.784	3/8	5/8 UNF X 1.25 DP

MOTORS	ALL SIZES			G0512	G0612	G0712	G0812
	G	KD	AB	K	K	K	K
56C	6.50	9.81	5.06	8.86	10.01	11.77	13.68
140T	6.50	10.69	6.12	8.86	10.01	11.77	13.68
180T	9.01	12.31	6.69	8.75	11.18	12.29	13.68
210T	9.01	16.38	7.94		11.18	12.29	13.68
250T	9.01	20.69	11.62			12.29	13.68